

# Final Reclamation Inspection

February 9, 2024

Operator: Blue Chip Oil Inc- 8840

Location ID: 327332

Inspection Document #: 697505109

Weld County, CO

Chris Binschus  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



**Photo 1.** Photo taken from the tank battery location, facing Northwest. Photo illustrates the entrance that was used for a mining operation. Tank battery and well location have been put back into irrigated crops in 2023.

Inspection Photos  
Location Name: SLOAN #3  
Location ID: 327332



**Photo 2.** Photo taken from the tank battery location, facing West. See comments under Photo 1.



**Photo 3.** Photo taken from the tank battery location, facing Southwest. Photo illustrates a silt pond constructed from mining operations.



Inspection Photos  
Location Name: SLOAN #3  
Location ID: 327332



**Photo 4.** Google Earth aerial imagery taken 10/19/2020 illustrating the Parsons Mine area in relation to oil and gas disturbance. Blue arrows indicate the approximate location of the well location, access road and tank battery.

