

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SENE

Location ID: 323966

Date: 2/12/2024



Wellhead/Site Degradation from Lack of Drainage – Photo #09196



Separator – Photo #09199

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SENE

Location ID: 323966

Date: 2/12/2024



Tank Battery – Photo #09198



Weathered Sign – Photo #09197