

Inspection Photos
Location Name: Brandt 43-13
Location ID: 309933



Photo 1 entrance to site



Photo 2 well head and equipment

Inspection Photos
Location Name: Brandt 43-13
Location ID: 309933




Photo 3 production equipment



Photo 4 production equipment

Inspection Photos
Location Name: Brandt 43-13
Location ID: 309933



Photo 5 tank battery



Photo 6 tank battery