

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

01/11/2024

Document Number:

403652192

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

OGCC Operator Number: 10254 Contact Person: Jacob Harter
Company Name: RED MESA HOLDINGS/O&G LLC Phone: (970) 946-3761
Address: 5619 DTC PARKWAY - STE 800 Fax: ()
City: GREENWOOD VILLAGE State: CO Zip: 80111 Email: jharter@cottonwoodconsulting.com

Identification Information

API Number: 05 - 067-09710 OGCC Facility ID: 374683 Initial Form 19 or 27 Document number: 403253981
Facility Name: HARRIS Facility Number: 5 (OWP) Facility Type: WELL
Location QtrQtr: SWSW Section: 22 Township: 33N Range: 12W Meridian:
County: LA PLATA Field Name: RED MESA
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: RED MESA HOLDINGS/O&G LLC Agent Name: Jacob Harter Title: Consultant
Phone Number: 970-946-3761 Email: jharter@cottonwoodconsulting.com

Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: Unlined Lined Fenced Netted

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 374683 Facility Name: HARRIS 5 (OWP) Facility Type:
Location: QtrQtr: SWSW Sec: 22 Twp: 33N Range: 12W Meridian: N
County Name: LA PLATA Latitude: 37.084300 Longitude: -108.144370

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 116135 Document Name: Size of file in bytes: 90112 File Name: Harris (OWP) #5 Soil Sample EDD (1).xls
Sample Type: Matrix:
Facility ID: 374683 Sample ID: 655392 Sample Name: Harris (OWP) #5 Sample Date: 10/25/2023
Collection Point: WellHead Matrix: SOIL Pre Post: Remediation
Project Number: Remediation Number: 27465 Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: Green Analytical Laboratories, Inc. Lab Sample ID: 2310256-01

Batch ID: 116139 Document Name: Size of file in bytes: 90112 File Name: Harris (OWP) #5 Soil Sample EDD (4).xls
 SampleType: _____ Matrix: _____
 Facility ID: 374683 Sample ID: 655397 Sample Name: Harris (OWP) #5 Sample Date: 11/15/2023
 Collection Point: PRODEQP Matrix: SOIL Pre Post: Remediation
 Project Number: _____ Remediation Number: 27465 Complaint Number: _____ NOAV Number: _____
 Inspection Number: _____ Spill Number: _____ Laboratory: Green Analytical Laboratories, Lab Sample ID: 2311208-01
 Inc.

Batch ID: 116137 Document Name: Size of file in bytes: 90112 File Name: Harris (OWP) #5 Soil Sample EDD (2).xls
 SampleType: _____ Matrix: _____
 Facility ID: 374683 Sample ID: 655395 Sample Name: Harris (OWP) #5 Sample Date: 10/25/2023
 Collection Point: PRODEQP Matrix: SOIL Pre Post: Remediation
 Project Number: _____ Remediation Number: 27465 Complaint Number: _____ NOAV Number: _____
 Inspection Number: _____ Spill Number: _____ Laboratory: Green Analytical Laboratories, Lab Sample ID: 2310256-02
 Inc.

Batch ID: 116138 Document Name: Size of file in bytes: 90112 File Name: Harris (OWP) #5 Soil Sample EDD (3).xls
 SampleType: _____ Matrix: _____
 Facility ID: 374683 Sample ID: 655396 Sample Name: Harris (OWP) #5 Sample Date: 10/25/2023
 Collection Point: PRODEQP Matrix: SOIL Pre Post: Remediation
 Project Number: _____ Remediation Number: 27465 Complaint Number: _____ NOAV Number: _____
 Inspection Number: _____ Spill Number: _____ Laboratory: Green Analytical Laboratories, Lab Sample ID: 2310256-03
 Inc.

Batch ID: 116140 Document Name: Size of file in bytes: 90112 File Name: Harris (OWP) #5 Soil Sample EDD (5).xls
 SampleType: _____ Matrix: _____
 Facility ID: 374683 Sample ID: 655398 Sample Name: Harris (OWP) #5 Sample Date: 11/15/2023
 Collection Point: PRODEQP Matrix: SOIL Pre Post: Remediation
 Project Number: _____ Remediation Number: 27465 Complaint Number: _____ NOAV Number: _____
 Inspection Number: _____ Spill Number: _____ Laboratory: Green Analytical Laboratories, Lab Sample ID: 2311208-02
 Inc.

Sample Facility Attachment:
 No Facility Attachment

Sample COGCC Well Related:
 No Sample COGCC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	The data submitted by the operator can be accessed through COGIS data system.	02/13/2024

Total: 1 comment(s)