



99999999

# DO OIL & GAS CONSERVATION COMMISSION FIELD INSPECTION REPORT

**S**ATISFACTORY INSPECTION

1120 Lincoln Street, Suite 801  
Denver, CO 80203  
(303)894-2100

NOTICE OF SATISFACTORY INSPECTION

API No. 05- (087 - 06742)		LEASE NAME: Schroe #1	
LOCATION: NESW 12-2N-58W		OPERATOR: Hewit	
DATE: 11-5-96		INSPECTOR: EBB	
Insp. Type: HR	Insp. Status: DA	PA: <input checked="" type="radio"/> N	Pass/Fail: <input checked="" type="radio"/> F
		Viol.: Y <input checked="" type="radio"/> N	NOV: Y <input type="radio"/> N

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210, 604.c(4))	<i>Bond release</i>	
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)		
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)		
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)		
<b>General Housekeeping</b> (Rule 603)		
<b>Spills (Oil/Water)</b> (Rule 907)		
<b>Bradenhead</b> (Rule 207.b)		
<b>Drilling Well/Workover</b> (Rule 317)		
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)	<i>grass</i>	
<b>Miscellaneous</b>		



**CORRECTIVE ACTION REQUIRED:**

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.



00080152