

Inspection Photos
Location Name: Wells Ranch 13, 14, 23-14 Tank Battery
Location ID: 472475



Photo 1 – Separator and ECDs



Photo 2 – Tank Battery



Inspection Photos
Location Name: Wells Ranch 13, 14, 23-14 Tank Battery
Location ID: 472475



Photo 3 – Tank Battery Sign



Photo 4 – Unmarked Riser

Inspection Photos
Location Name: Wells Ranch 13, 14, 23-14 Tank Battery
Location ID: 472475



Photo 5 – Unmarked Riser and Tumbleweeds



Photo 6 – Unmarked Riser and Unused Chemical Tank

Inspection Photos
Location Name: Wells Ranch 13, 14, 23-14 Tank Battery
Location ID: 472475



Photo 7 – Tumbleweeds at ECD



Photo 8 – Unmarked Riser