

Inspection Photos

Location Name: TEP Rocky Mountain LLC SAVAGE RMV 180-29 Pad

Location # 324097



Photo # 6375 From entrance to location




Photo # 6376 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC SAVAGE RMV 180-29 Pad

Location # 324097



Photo # 6377 Location



Photo # 6378 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC SAVAGE RMV 180-29 Pad

Location # 324097



Photo # 6379 Location



Photo # 6380 Location