

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/12/2024

Submitted Date:

02/13/2024

Document Number:

707602410

FIELD INSPECTION FORM

Loc ID 305098 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Binschus, Chris		chris.binschus@state.co.us	
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274140	WELL	PA	07/31/2019	OW	123-22440	OCOMA B 31-23	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Battery: Abandoned. ALL equipment has been removed.
Abandoned Battery SE corner GPS coordinates: 40.348609 / -104.590133

Abandoned Centralized Battery Formerly served 3 Location IDs
(323704, 305098, 323703).
(Well(s): 3: Plugged & Abandoned | PA).

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	corrective date
Type: Gas Meter Run	# 0	
Comment:	Plugged & Abandoned PA. Battery Abandoned. Equipment removed.	
Corrective Action:		Date:
Type: Emission Control Device	# 0	
Comment:	Plugged & Abandoned PA. Battery Abandoned. Equipment removed.	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 0	
Comment:	Plugged & Abandoned PA. Battery Abandoned. Equipment removed.	
Corrective Action:		Date:
Type: Plunger Lift	# 0	
Comment:	Plugged & Abandoned PA. Equipment removed.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				
Comment:	Plugged & Abandoned PA. Battery Abandoned. Equipment removed.				
Corrective Action:					Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	<input type="text"/>			

Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				
Comment: Plugged & Abandoned PA. Battery Abandoned. Equipment removed.					
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No					
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 274140 Type: WELL API Number: 123-22440 Status: PA Insp. Status: PA

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On MON 02/12/2024 at approximately 14:52 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: OCOMA B-65N64W/31SESE Location ID: 305098 Well Name(s): Ocoma B 31-23. API: 123-22440. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.348609 / -104.590133</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Form 6-SRA on file. Plugging, cut/cap date: 07/31/2019. Approved. Plugged & Abandoned PA well GPS coordinates: 40.351320 / -104.587520</p> <p>Routine inspection.</p>	evinsb	02/13/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602411	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6429070