

Inspection Photos
Location Name: Spade 1-12
Location ID: 319612



Energy & Carbon Management Commission
40.40245, -104.9444, 1490.0m, 19°
02/14/2024 09:33:11

Production facility and debris



Energy & Carbon Management Commission
40.40251, -104.94435, 1468.0m, 85°
02/14/2024 09:34:19

Battery sign

Inspection Photos
Location Name: Spade 1-12
Location ID: 319612



Debris



Debris

Inspection Photos
Location Name: Spade 1-12
Location ID: 319612



Unused equipment



Unused equipment

Inspection Photos
Location Name: Spade 1-12
Location ID: 319612



Wellhead sign