

# Inspection Photos

Loc: 307979

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection Date: 2/12/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing north toward wellsite location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:307979 | Date: 2/12/2024



## Inspection Photos



**Photo 2.** Facing north along the fill slope which is stabilized with vegetation.





## Inspection Photos



**Photo 3.** There is oily fluid leak at the pumpjack.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:307979 | Date: 2/12/2024