

Inspection Photos

Loc: 307486

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection Date: 2/13/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west toward wellsite location.



Inspection Photos



Photo 2. Facing toward the wellhead. There are stained soils at wellhead and separator that need to be cleaned up.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:307486 | Date: 2/13/2024

Inspection Photos



Photo 3. There is stained soils around the wellhead from a recent spill..



Inspection Photos



Photo 4. Facing southwest. The shed needs to be put back into use or removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:307486 | Date: 2/13/2024