

# Inspection Photos

Loc: 307470

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection Date: 2/12/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west toward wellsite location.



Inspection Photos



**Photo 2.** The fence around the pit is in disrepair..



Inspection Photos



**Photo 3.** Well sign is posted at the meter shed.

