

Final Reclamation Inspection

February 9, 2024

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 319611

Inspection Document #: 697505123

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HAAS 1
Location ID: 319611



Photo 1. Photo taken from the associated off-location tank battery, facing East. Photo illustrates a land use change to housing development. All oil and gas equipment has been removed.



Inspection Photos
Location Name: HAAS 1
Location ID: 319611



Photo 2. Photo taken from the well location, facing South. See comments under Photo 1.

