

Inspection Photos

Loc: 307975

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 2/12/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:307975 | Date: 2/12/2024

Inspection Photos



Photo 2. Facing toward the onsite pit which is fenced.



Inspection Photos



Photo 3. It appears stained soils have been cleaned up at the meter shed.

