

Operator: Extraction Oil and Gas
Location Name: BOXELDER A-61S65W 35SENE
Loc ID: 319821
Inspection: 709400777



Exhibit A



Exhibit B



Exhibit C



Exhibit D

CA: Failure to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands. Comply with Rule 606.

CA Resolution: Weeds have been managed to comply with Rule 606.