

Operator: Extraction Oil and Gas

Location Name: CHAMPLIN 78 AMOCO A-61S65W 35NESE

Loc ID: 319725

Inspection: 709400775



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E

CA: Failure to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands. Comply with Rule 606.

CA Resolution: Weeds have been managed to comply with Rule 606.