

Operator: Bonanza Creek Energy
Location Name: Wells Ranch 13, 14, 23, 24-14
Loc ID: 472475
Inspection: 696305964



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E




Exhibit F

CA: Tumbleweeds at ECDs. See photos Comply with Rule 606

CA Resolution: Tumbleweeds have been removed to comply with Rule 606.

CA: Unmarked Risers at Separator. See photos Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.

CA Resolution: Risers have been marked to comply with Rule 1105.

CA: Unused Chemical Tank, Injection Pump and Containment at Separator. See photos Comply with Rule 606

CA Resolution: Unused equipment has been removed to comply with Rule 606.