

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NENW

Location ID: 324051

Date: 2/12/2024



Location Entrance – Photo #09226



Location Entrance – Photo #09227

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NENW

Location ID: 324051

Date: 2/12/2024



Wellhead – Photo #09221



Separators – Photo #09223

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NENW

Location ID: 324051

Date: 2/12/2024



Tank Battery – Photo #09224



Weathered Wellhead Sign – Photo #09222



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NENW

Location ID: 324051

Date: 2/12/2024



Lack of Stabilization – Photo #09228



Lack of Stabilization/Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #09229