

Final Reclamation Inspection

February 13th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333844

Inspection Document #: 714000407

La Plata County, CO

Township: NENW 34 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Hronich 21-34 1, 3
Location ID: 333844

2/13/24
+37.152346,-107.708008
44° NE




Photo 1. View of the disturbance from the entrance facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07710, 09624

Inspection Photos
Location Name: Hronich 21-34 1, 3
Location ID: 333844



2/13/24
+37.152372,-107.708128
225° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the southern interim reclamation area facing southwest.
Interim is dominated by gramma and crested wheatgrass.

API #: 067-07710, 09624

Inspection Photos
Location Name: Hronich 21-34 1, 3
Location ID: 333844



Photo 3. View of surface owner trailer and hay stored on the western and eastern edges of the disturbance.

Inspection Photos

Location Name: Hronich 21-34 1, 3

Location ID: 333844



Photo 4. Produced water sign capacity and berm maintenance CA identified in previous inspection have both been addressed/resolved.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07710, 09624

Inspection Photos

Location Name: Hronich 21-34 1, 3

Location ID: 333844



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of woody tree debris in the western interim reclamation area.

API #: 067-07710, 09624

Inspection Photos
Location Name: Hronich 21-34 1, 3
Location ID: 333844



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. View of weedy kochia debris observed in the northeast corner of the disturbance.

API #: 067-07710, 09624

Inspection Photos
Location Name: Hronich 21-34 1, 3
Location ID: 333844



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Reference area is comprised of juniper with a heavily grazed understory.

API #: 067-07710, 09624