

# Final Reclamation Inspection

February 13th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326349

Inspection Document #: 714000408

La Plata County, CO

Township: NENW 27 34N 8W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**


**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Lamke A1, A3  
Location ID: 326349



Photo 1. View of the disturbance from the entrance facing center.



API #: 067-07890, 09761



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Lamke A1, A3  
Location ID: 326349

2/13/24  
+37.166829,-107.708516  
214° SW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of the northern interim reclamation area facing north. Area dominated by intermediate and crested wheatgrass.

API #: 067-07890, 09761

Inspection Photos  
Location Name: Lamke A1, A3  
Location ID: 326349

2/13/24  
+37.166348,-107.708283  
249° W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** View of weedy kochia debris dominating the western interim reclamation area.

API #: 067-07890, 09761

Inspection Photos  
Location Name: Lamke A1, A3  
Location ID: 326349



**Photo 4.** View of impacted material and weedy debris at well head A3.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-07890, 09761

Inspection Photos  
Location Name: Lamke A1, A3  
Location ID: 326349



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** Reference area comprised of smooth brome.

API #: 067-07890, 09761