

Final Reclamation Inspection

February 13th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306878

Inspection Document #: 714000409

La Plata County, CO

Township: SWSW 22 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McManus 33-22 2
Location ID: 306878

2/13/24
+37.172333,-107.710112
125° SE



2/13/24
+37.172333,-107.710112
75° E

Photo 1. View of the disturbance from the entrance facing center.

Inspection Photos
Location Name: McManus 33-22 2
Location ID: 306878

2/13/24
+37.172371,-107.709713
22° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the eastern interim reclamation area facing north.

API #: 067-08945

Inspection Photos
Location Name: McManus 33-22 2
Location ID: 306878



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of trash that remains in the eastern interim reclamation area.

API #: 067-08945

Inspection Photos

Location Name: McManus 33-22 2

Location ID: 306878



2/13/24
+37.172371,-107.709713
13° N



2/13/24
+37.172482,-107.709712
221° SW

Photo 4. View of impacted materials at the well head and exhaust muffler.

Inspection Photos
Location Name: McManus 33-22 2
Location ID: 306878

2/13/24
+37.172842,-107.710128
356° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area comprised of dormant grasses.

API #: 067-08945