

# Final Reclamation Inspection

February 13th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326245

Inspection Document #: 714000410

La Plata County, CO

Township: NENW 22 34N 8W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Black 21-22 1  
Location ID: 326245

2/13/24  
+37.181797,-107.705921  
205° SW



Photo 1. View of the disturbance from the entrance facing center.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-07705

Inspection Photos  
Location Name: Black 21-22 1  
Location ID: 326245



**Photo 2.** View of eastern interim reclamation area facing north comprised of western wheatgrass. No weeds were observed during this inspection.

Inspection Photos  
Location Name: Black 21-22 1  
Location ID: 326245



**Photo 3.** View of rill erosion forming on the southern edge of the disturbance.

Inspection Photos  
Location Name: Black 21-22 1  
Location ID: 326245




**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** View of unused oil and gas gates stored on the western edge of the disturbance.

API #: 067-07705

Inspection Photos  
Location Name: Black 21-22 1  
Location ID: 326245



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** View of impacted material at the well head.

API #: 067-07705

Inspection Photos  
Location Name: Black 21-22 1  
Location ID: 326245

2/13/24  
+37.182309,-107.705329  
102° E



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** View of reference area comprised of poa secunda, sagebrush and juniper.

API #: 067-07705