

# Final Reclamation Inspection

February 13th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333970

Inspection Document #: 714000411

La Plata County, CO

Township: SENE 22 34N 8W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Black 21-22 2, 4  
Location ID: 333970



2/13/24  
+37.183574,-107.705173  
107° E



Photo 1. View of the disturbance from the entrance facing center.

Inspection Photos  
Location Name: Black 21-22 2, 4  
Location ID: 333970



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of northern interim reclamation area facing northeast. Comprised of intermediate wheatgrass.

API #: 067-09018, 09600

Inspection Photos  
Location Name: Black 21-22 2, 4  
Location ID: 333970



Photo 3. View of unused oil and gas equipment observed on location.

Inspection Photos  
Location Name: Black 21-22 2, 4  
Location ID: 333970



Photo 4. Additional unused oil and gas equipment observed on location.



Inspection Photos  
Location Name: Black 21-22 2, 4  
Location ID: 333970



**Photo 5.** View of surface owner farming equipment stored in the eastern and western interim reclamation areas.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-09018, 09600

Inspection Photos  
Location Name: Black 21-22 2, 4  
Location ID: 333970



**Photo 6.** View of impacted surface material at well head #2.



Inspection Photos  
Location Name: Black 21-22 2, 4  
Location ID: 333970

2/13/24  
+37.179425,-107.700154  
230° SW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 7.** View of reference area comprised of smooth brome and sagebrush.

API #: 067-09018, 09600