

# Final Reclamation Inspection

February 13th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333433

Inspection Document #: 714000413

La Plata County, CO

Township: SESE 31 34N 7W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Buford Wayt A1, A3  
Location ID: 333433

2/13/24  
+37.143714,-107.644440  
84° E



Photo 1. View of the disturbance from the entrance facing center.





# Inspection Photos

Location Name: Buford Wayt A1, A3

Location ID: 333433



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** Produced water tank CA identified in previous inspection doc #702500125 has been addressed/resolved.

API #: 067-06875, 09443



Inspection Photos

Location Name: Buford Wayt A1, A3

Location ID: 333433



2/13/24

+37.143139,-107.643907

21° N



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Unused oil and gas fencing equipment stored on location.

API #: 067-06875, 09443



Inspection Photos

Location Name: Buford Wayt A1, A3

Location ID: 333433



2/13/24

+37.143663,-107.643647

190° S

**Photo 4.** Reference area is an open pasture.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-06875, 09443