

Inspection Photos
Location Name: Wailes 2
Location ID: 320125




Pic 1 wellhead sign is in need of phone number



Pic 2 Pumpjack / wellhead

Inspection Photos
Location Name: Wailes 2
Location ID: 320125



Pic 3 Flowlines appear to be in the open position



Pic 4 unused equipment needs to removed.