

Inspection Photos

Loc: 431589

Operator: PIONEER NATURAL RESOURCES USA INC

Inspection Date: 2/13/2024

County: LINCOLN



Inspection Photos



Photo 1. Facing south toward the access road which has been mowed and maintained.



Inspection Photos



Photo 2. Facing south toward the location which is fenced.



Inspection Photos




Photo 3. Facing north toward the access road. The dark vegetation is undesirable weed cover (Kochia) and the light color is desirable vegetation.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:431589 | Date: 2/13/2024

Inspection Photos



Photo 4. Center of the location facing south. The location has been mowed but there is mostly undesirable weed growth throughout the location.



Inspection Photos



Photo 5. Center of the location facing east.



Inspection Photos



Photo 6. Center of the location Facing west.



Inspection Photos



Photo 7. View of groundcover shows mostly undesirable weeds. Red arrows point to some desirable species but are insufficient cover.



Inspection Photos



Photo 8. Facing east toward the surrounding undisturbed pasture.

