

# Inspection Photos

Loc: 454833

Operator: K3 OIL & GAS OPERATING COMPANY

Inspection Date: 2/13/2024

County: LINCOLN



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing north at the access road off the county road. The fence needs to be reinstalled back to the original position.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:454833 | Date: 2/13/2024



## Inspection Photos



**Photo 2.** Facing northeast toward the location which is fenced off however the gate is broken and does not prevent livestock entry.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:454833 | Date: 2/13/2024



## Inspection Photos



**Photo 3.** Facing north at the location. There are mostly undesirable weeds throughout the location that need to be controlled.





## Inspection Photos



**Photo 4.** Facing west at the center of the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:454833 | Date: 2/13/2024



## Inspection Photos



**Photo 5.** Facing south at the center of the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:454833 | Date: 2/13/2024



## Inspection Photos



**Photo 6.** Facing east at the center of the location.





## Inspection Photos



**Photo 7.** View of ground cover shows mostly undesirable weeds (Kochia).

