

# Inspection Photos

Loc: 455067

Operator: K3 OIL & GAS OPERATING COMPANY

Inspection Date: 2/13/2024

County: LINCOLN



## Inspection Photos



**Photo 1.** Facing east at the access road off the county road. The fence needs to be reinstalled back to the original position.



Inspection Photos



**Photo 2.** Facing east toward the location which is fenced off.



## Inspection Photos



**Photo 3.** Facing southeast at the location. There are mostly undesirable weeds throughout the location that need to be controlled.



Inspection Photos



**Photo 4.** Facing north at the center of the location.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:455067 | Date: 2/13/2024

## Inspection Photos



**Photo 5.** Center of the location facing east. The east side of the location appears to have more desirable vegetation establishing.



## Inspection Photos



**Photo 6.** Center of the location facing west. The west side of the location consists mostly of undesirable weeds.



## Inspection Photos



**Photo 7.** View of ground cover shows mostly undesirable weeds (Kochia).

