

Final Reclamation Inspection

February 13th, 2024

Operator: Simcoe LLC - 10749

Location ID: 334276

Inspection Document #: 714000426

La Plata County, CO

Township: SWSE 13 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Neil 34-13 1, 3
Location ID: 334276



Photo 1. View of the disturbance from the entrance facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09187, 07778

Inspection Photos
Location Name: Neil 34-13 1, 3
Location ID: 334276



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Produced water sign CA identified in previous inspection doc #712700239 has been addressed/resolved.

API #: 067-09187, 07778

Inspection Photos
Location Name: Neil 34-13 1, 3
Location ID: 334276



Photo 3. View of unused oil and gas fencing on location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09187, 07778

Inspection Photos
Location Name: Neil 34-13 1, 3
Location ID: 334276

2/13/24
+37.187254,-107.666042
220° SW



Photo 4. View of woody debris and piles of grazel on the western edge of the disturbance.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09187, 07778

Inspection Photos
Location Name: Neil 34-13 1, 3
Location ID: 334276



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of unused piping debris stored on the western edge of the disturbance.

API #: 067-09187, 07778

Inspection Photos
Location Name: Neil 34-13 1, 3
Location ID: 334276

2/13/24
+37.186518,-107.666132
162° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. View of irrigated grass field reference area.

API #: 067-09187, 07778