

# Final Reclamation Inspection

February 13th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333449

Inspection Document #: 714000427

La Plata County, CO

Township: NESW 13 34N 8W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Neil 34-13 2, 4  
Location ID: 333449



2/13/24  
+37.188393,-107.671971  
154° SE



Photo 1. View of the disturbance from the entrance facing center.


Inspection Photos  
Location Name: Neil 34-13 2, 4  
Location ID: 333449



**Photo 2.** Metal debris and woody debris observed on the eastern edge of the disturbance.



Inspection Photos  
Location Name: Neil 34-13 2, 4  
Location ID: 333449



**Photo 3.** Weedy russian thistle debris observed in the eastern interim/fill slope.

Inspection Photos  
Location Name: Neil 34-13 2, 4  
Location ID: 333449

2/13/24  
+37.188879,-107.672156  
352° N

