

Inspection Photos
Location Name: Lansons Farm 5
Location ID: 317930



Photo 1 Location.

Photo 2 WO rig, accumulator trailer, heater.

Inspection Photos
Location Name: Anderson MB 33-6
Location ID: 321422



Photo 3 Rig pump.



Photo 4 Fresh water, circulation tanks.

Inspection Photos
Location Name: Anderson MB 33-6
Location ID: 321422



Photo 5 Rig floor, tubing and casing trailers .

Photo 6 BOP, WH.

Inspection Photos
Location Name: Anderson MB 33-6
Location ID: 321422



Photo 7 Location.