



Photos  
taken by  
Kris  
Neidel

Location  
: 428915  
REM:  
7037



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo #1 looking to the northwest at MW09. CDH staff  
collecting water sample.**



Photos  
taken by  
Kris  
Neidel

Location  
: 428915  
REM:  
7037



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Photo #2 CDH staff collecting water sample from MW03R



Photos  
taken by  
Kris  
Neidel

Location  
: 428915  
REM:  
7037



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources


**Photo #3 purged water was collected in bucket, it was stated that IDW would be left with KPK to dispose as PW.**



Photos  
taken by  
Kris  
Neidel

Location  
: 428915  
REM:  
7037





Photos  
taken by  
Kris  
Neidel

Location  
: 428915  
REM:  
7037

