

Interim Reclamation and Stormwater Inspection

Date: 2/14/24

Operator: Noble Energy Inc. - 100322

Location ID: 323719

Inspection Document #: 713900366

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Ocoma G25-10
Location ID: 323719



Photo 1. The photo was taken at the tank battery location facing North. The photo illustrates the operator sign.

Inspection Photos
Location Name: Ocoma G25-10
Location ID: 323719




Photo 2. The photo was taken at the tank battery location facing Northeast. The photo illustrates the a diversion ditch running West to East along the center of the location.



Photo 3. The photo was taken from the tank battery location facing Northwest. The photo illustrates where the ditch runs to a section of rip rap and shows erosion around the outer edge as well as rilling erosion running down the pad to the North.

Inspection Photos
Location Name: Ocoma G25-10
Location ID: 323719



ECMC
279° W
2/14/24, 10:29 AM

Photo 4. The photo was taken from the tank battery location facing West. The photo illustrates the continued erosion along the pad.



ECMC
177° S
2/14/24, 10:31 AM

Photo 5. The photo was taken at the tank battery location facing South. The photo illustrates erosion on the West side of the facility flowing sediment beyond the disturbance boundary fence.