

Inspection Photos

Location Name: Owl Creek 8-64-30

Location ID: 423948 Spill ID: 486067



Photo 1 Overview of Spill area east side of heater treater building



Photo 2 Overview of Spill area north side of heater treater building



Inspection Photos

Location Name: Owl Creek 8-64-30

Location ID: 423948 Spill ID: 486067



Photo 3 Overview of Spill area north side of heater treater building



Photo 4 Location of corroded bull plug on heater treater

Inspection Photos

Location Name: Owl Creek 8-64-30

Location ID: 423948 Spill ID: 486067




Photo 5 Corroded bull plug



Photo 6 South end of tank battery / removed tanks. Liner repair / seam visible on containment wall



Inspection Photos

Location Name: Owl Creek 8-64-30

Location ID: 423948 Spill ID: 486067



Photo 7 view of liner repair / seam in tank battery containment



Photo 8 view of liner repair / seam in tank battery containment



Inspection Photos
Location Name: Owl Creek 8-64-30
Location ID: 423948 Spill ID: 486067



Photo 9 Crude Oil AST, faded labeling



Photo 10 Produced Water AST, faded labeling

Inspection Photos
Location Name: Owl Creek 8-64-30
Location ID: 423948 Spill ID: 486067



Photo 11 Wellhead area



Photo 12 Wellhead, leaky fittings