

# Interim Reclamation and Stormwater Inspection

Date: 2/14/24

Operator: Noble Energy Inc. - 100322

Location ID: 428827

Inspection Document #: 713900374

Weld County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Shelton PC G25-74-1HN Pad

Location ID: 428827



**Photo 1.** The photo was taken at the well location facing Northeast. The photo illustrates the producing wells and some area of interim.

**Photo 2.** The photo was taken at the well location facing East. The photo illustrates the interim areas are being managed by evidence of mowing activities.



## Inspection Photos

Location Name: Shelton PC G25-74-1HN Pad

Location ID: 428827



**Photo 3.** The photo was taken at the well location facing Northwest. The photo illustrates the access road has no current stormwater issues.



**Photo 4.** The photo was taken at the tank battery facility facing East. The photo illustrates the North side of the production facility.




## Inspection Photos

Location Name: Shelton PC G25-74-1HN Pad

Location ID: 428827



**Photo 5.** The photo was taken at the tank battery facility facing Southwest. The photo illustrates the small tank does not have proper tank labels. The photo is representative of 4 other tanks that are missing labels or the labels have faded and are illegible.



**Photo 6.** The photo was taken at the tank battery facility facing Southeast. The photo illustrates the East side of the production facility as well as the interim slope has been stabilized and is being actively managed with evidence of mowing.



## Inspection Photos

Location Name: Shelton PC G25-74-1HN Pad

Location ID: 428827



**Photo 7.** The photo was taken at the tank battery facility facing West. Refer to the comment for photo 6.



**Photo 8.** The photo was taken at the tank battery facility facing East. The photo illustrates the portable toilet has been secured by bailing twine which may be inadequate.



## Inspection Photos

Location Name: Shelton PC G25-74-1HN Pad

Location ID: 428827



**Photo 9.** The photo was taken at the tank battery facility facing West. The photo illustrates discharge hose being stored within the interim.



**Photo 10.** The photo was taken at the tank battery facility facing Northwest. The photo illustrates the sediment trap at the Southwest end of the facility.