

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 11-28

Location ID: 433948

Date: 2/13/2024



Location Entrance – Photo #09254



Wellheads – Photo #09255

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 11-28

Location ID: 433948

Date: 2/13/2024



Feb 13, 2024 at 15:32:35



Feb 13, 2024 at 15:33:23

Separators – Photo #09256

Tank Battery – Photo #09258

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 11-28

Location ID: 433948

Date: 2/13/2024



Open-Ended Load Line – Photo #09259



Lack of Stabilization – Photo #09257

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 11-28

Location ID: 433948

Date: 2/13/2024



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09260