

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWSW

Location ID: 334788

Date: 2/15/2024



Wellheads – Photo #09313




Separators – Photo #09315

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWSW

Location ID: 334788

Date: 2/15/2024



Tank Battery – Photo #09310



Lack of Stabilization – Photo #09312

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWSW

Location ID: 334788

Date: 2/15/2024



Lack of Stabilization – Photo #09314



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09316**