

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESW

Location ID: 334812

Date: 2/15/2024



Feb 15, 2024 at 15:38:51
De Beque CO 81630
United States



Feb 15, 2024 at 15:39:20
De Beque CO 81630
United States

Location Entrance – Photo #09318

Wellheads – Photo #09319

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESW

Location ID: 334812

Date: 2/15/2024



Separators – Photo #09322



Tank Battery – Photo #09321

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NESW

Location ID: 334812

Date: 2/15/2024



Lack of Stabilization – Photo #09320



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09325**