

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SENW

Location ID: 334882

Date: 2/15/2024



Location Entrance – Photo #09327

Wellheads – Photo #09328



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SENW

Location ID: 334882

Date: 2/15/2024



Separators – Photo #09331



Tank Battery – Photo #09330



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SENW

Location ID: 334882

Date: 2/15/2024



Feb 15, 2024 at 15:51:02  
De Beque CO 81630  
United States



Feb 15, 2024 at 15:52:53  
De Beque CO 81630  
United States

**Lack of Stabilization – Photo #09329**

**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #09332**