

Hein Hart WH Photo Log

Location ID: 307094

January 30, 2024

Title/Sample ID:

East pit facing west. Weeds removed, fencing surrounding the area has been repaired.



Title/Sample ID:

East pit facing east. Weeds removed and fencing repaired.



Title/Sample ID:

West pit facing southwest. Weeds removed and fencing repaired.



Title/Sample ID:

West pit facing southeast. Weeds removed Fencing repaired.

