

# Inspection Photos

2/13/2024

**Operator:** CAERUS PICEANCE LLC #10456

**Location ID:** 439135

**Inspection Doc:** 696205605

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 439135



**Photo 1:** Photos taken from the Location entrance, facing east and southeast. Photos provide an overview of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 439135



February 13, 2024

**Photo 2:** Tank battery signage pursuant to Rule 605.e is missing, or not conspicuously posted at the battery



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 439135



February 13, 2024

**Photo 3:** Unused fence panels.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 439135



**Photo 4:** Sanitary Facilities (Porta-johns) not secured.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources