

Inspection Photos

Loc: 307861

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection Date: 2/16/2024

County: LAS ANIMAS



Inspection Photos



Photo 1. Facing west at beginning of the road. It appears a new culvert was installed at this area.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:307861 | Date: 2/16/2024

Inspection Photos



Photo 2. Facing northwest. The culvert near the wellsite has been repaired.



Inspection Photos



Photo 3. Facing northwest at the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:307861 | Date: 2/16/2024

Inspection Photos



Photo 4. Facing toward the wellhead.

