

# Inspection Photos

Loc: 333421

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection Date: 2/16/2024

County: LAS ANIMAS



Inspection Photos



**Photo 1.** Facing southeast along the access road . This culvert is filled in with sediment causing erosion of the road..



Inspection Photos



**Photo 2.** There is erosion across the road at the intersection where culvert is plugged.,



Inspection Photos



**Photo 3.** Facing southeast toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:333421 | Date: 2/16/2024