

Inspection Photos

Loc: 309066

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection Date: 2/16/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest along the access road. There is vehicle rutting and the road is not stabilized along this area.



Inspection Photos



Photo 2. Facing northeast along the access road. There is vehicle rutting and the road is not stabilized along this area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309066 | Date: 2/16/2024

Inspection Photos



Photo 3. Facing northeast toward the wellsite. There are area areas of vehicle rutting.



Inspection Photos



Photo 4. Facing east toward the wellsite. There are area areas of vehicle rutting.

