

Inspection Photos

Loc: 307865

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection Date: 2/16/2024

County: LAS ANIMAS



Inspection Photos



Photo 1. Facing southwest along the access road. There is vehicle rutting and poor drainage along this area.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:307865 | Date: 2/16/2024

Inspection Photos



Photo 2. Facing southwest along the access road. There is vehicle rutting and poor drainage along this area.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:307865 | Date: 2/16/2024

Inspection Photos



Photo 3. Facing southwest along the access road. There is vehicle rutting along the road which is not stabilized in areas.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:307865 | Date: 2/16/2024

Inspection Photos



Photo 4. Facing southwest toward the wellsite.

