

KP Kauffman - ECMC Inspection Photos
Location: Facility #4 at Ditlev C1 Flowline Release
Spill ID #485898 Date 02/15/2024



Signage at Ditlev Simonsen C 1 Well



**Fenced excavation at flowline release; flowlines exposed.
View looking south.**

KP Kauffman - ECMC Inspection Photos
Location: Facility #4 at Ditlev C1 Flowline Release
Spill ID #485898 Date 02/15/2024



(2) HDPE flowlines with tracer wire installed; sliplined to south through cut/ existing 6" facility 4 carbon steel pipe.
(1) existing 2" carbon steel natural gas flowline also seen.



View from excavation adjacent to wellhead to south end of the repair section; field work in progress.