

Inspection Photos

2/13/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335922

Inspection Doc: 696205606

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335922



Photo 1: Photos taken from the Location entrance, facing east and southeast. Photos provide an overview of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335922



Photo 2: Tank battery signage pursuant to Rule 605.e is missing, or not conspicuously posted at the battery



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335922



Photo 3: Line at tank missing cap/plug.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources