

Inspection Photos

2/13/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335887

Inspection Doc: 696205610

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources


Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335887



February 13, 2024



February 13, 2024

Photo 1: Photos taken from the Location entrance, facing northwest and northeast. Photos provide an overview of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335887




Photo 2: Photo shows signage is missing from the well.




COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335887



February 13, 2024



February 13, 2024

Photo 3: Wildlife protection BMPs missing from the secondary containment of the two methanol tanks on the Location



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335887



Photo 4: Photos examples showing fence along perimeter of the pad is in disrepair.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335887



Photo 5: Signage not observed at the tank battery facility; signage missing, or not conspicuously posted at the battery facility.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources