

Final Reclamation Inspection

February 16th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326333

Inspection Document #: 714000435

La Plata County, CO

Township: SESE 2 34N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Federal 01-02 1
Location ID: 326333



Photo 1. View of the disturbance from the entrance facing center.

Inspection Photos
Location Name: Federal 01-02 1
Location ID: 326333



Photo 2. View of the western interim reclamation area facing northwest.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07853

Inspection Photos
Location Name: Federal 01-02 1
Location ID: 326333



Photo 3. View of wattle debris and wattles that are no longer functioning in the northwestern project area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07853

Inspection Photos
Location Name: Federal 01-02 1
Location ID: 326333



Inspection Photos
Location Name: Federal 01-02 1
Location ID: 326333



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of rill erosion forming along the western edge of the access road.

API #: 067-07853

Inspection Photos
Location Name: Federal 01-02 1
Location ID: 326333



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Impacted surface material observed at the well head.

API #: 067-07853

Inspection Photos
Location Name: Federal 01-02 1
Location ID: 326333



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 7. Reference area comprised of juniper and smooth brome/indian ricegrass.

API #: 067-07853