

Final Reclamation Inspection

February 16th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306919

Inspection Document #: 714000437

La Plata County, CO

Township: NESE 12 34N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Dry Creek Federal 2
Location ID: 306919



Photo 1. View of the disturbance from the entrance facing center.



API #: 067-09047

Inspection Photos
Location Name: Dry Creek Federal 2
Location ID: 306919

2/16/24
+37.228593,-107.691055
287° W



Photo 2. View of the northern interim reclamation area facing west.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09047

Inspection Photos
Location Name: Dry Creek Federal 2
Location ID: 306919



Photo 3. View of kochia debris observed around the equipment and in the southeast corner of the disturbance.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09047

Inspection Photos
Location Name: Dry Creek Federal 2
Location ID: 306919



Photo 4. View of rill erosion forming in the southeast interim reclamation area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09047

Inspection Photos
Location Name: Dry Creek Federal 2
Location ID: 306919



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Impacted surface material CA identified in the previous inspection doc #687905226 has been addressed/resolved. Weedy debris observed around well head.

API #: 067-09047

Inspection Photos
Location Name: Dry Creek Federal 2
Location ID: 306919

